



• THE NATURE SERIES •

EXTERIOR WOOD DOORS

(LIMITED 1 YEAR WARRANTY)

Bayer Built Woodworks, Inc. warrants the original owner a period of 1 year from date of the invoice that all Nature Series doors are free of defects in material and workmanship that might unreasonably affect its performance as follows:

- Splits in door panels in excess of 1/16" inch in width
- Delaminating of stiles and rails in (lifting of veneer)
- Warping of doors in excess of 1/4" inch
- Separation of stiles and rails in excess of 1/16" inch in width

In case of warp or stile/rail separation door must be allowed to hang through a full heating and cooling season.

Placement of your wood door is a major factor in performance; the proper overhang is required to provide necessary protection from the exterior elements. Proper care and storage should be considered when handling this product.

This Warranty Does Not Cover:

- Failure to follow installation or care and maintenance instructions
- Finish must be maintained for warranty to be valid
- Placing a door without providing proper overhang. Overhang distance should be half of your overhang height (minimum)
- Any doors that have been cut-down in size or altered from original state
- Appearance of field finishing
- Damage caused by failing to seal all six sides of the door within 72 hours of hanging
- Caming is handcrafted so slight imperfections are acceptable
- Excess glazing on door glass
- Scratched glass from improper cleaning or handling
- Damage caused by attempting to repair the product
- Damages caused by others or by any cause beyond the control of Bayer Built Woodworks, including normal wear and tear, customer misuse, abuse, fire, flood, storm or other acts of nature
- All components, parts, glass and labor supplied by anyone other than Bayer Built Woodworks
- Exposure to acids, chemicals or fumes
- Fading or discoloration due to UV or sunlight exposure
- Doors that are over 3'-6" in width and/or 8'-0" in height
- Doors larger than 3'-0" x 7'-0" without a multi-point locking mechanism
- Natural variations in the color and/or texture of the wood
- Panel misalignment or shrinkage of 1/4" or less
- Expansion of bottom rail due to climate conditions
- Variation in stain absorption due to grain, color or texture
- Damage caused by extreme temperature build-up where a storm door or dark paint or stain is utilized
- Storm doors must be vented, excessive heat build up can cause finishing problems and warping

Proper storage, finishing, care and maintenance are required for warranty coverage.

Bayer Built Woodworks maximum liability is the purchase price of the product; Finishing and installation costs are not covered by warranty.

Final credit approval will be given after Bayer Built Woodwork's inspection process.

BAYER BUILT SPECIFICALLY EXCLUDES ALL OTHER WARRANTIES, EXPRESS OR IMPLIED INCLUDING BUT NOT LIMITED TO, THE IMPLIED WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

BUYERS SOLE AND EXCLUSIVE REMEDY FOR DAMAGES IS EITHER REPAIR OR REPLACEMENT OF THE PRODUCT AND SELLER SPECIFICALLY EXCLUDES ANY DAMAGES INCLUDING, BUT NOT LIMITED TO CONSEQUENTIAL OR INCIDENTAL DAMAGES.