



Warranty Information

QUALITY MILLWORK, UNBELIEVABLE SERVICE!

24614 US HWY 71 • BELGRADE, MN 56312

PH 320.254.3651

FX 320.254.3601

WWW.BAYERBUILT.COM

Interior Panel, French, Louver & Café Doors 1-3/8" & 1-3/4"

(Limited 1 Year Warranty)

Bayer Built Woodworks, Inc. provides a limited warranty to the original owner for one year from the date of the original invoice as long as proper installation, care, and maintenance guidelines are followed. This warranty covers defects in material and workmanship that may unreasonably affect a door's performance, including, but not limited to, the following:

- · Separation of skins from door's core
- Splits in door panels in excess of 1/16" inch in width
- Separation of stiles and rails in excess of 1/16" inch in width
- Warping of doors in excess of 1/4" inch

In case of a warping or stile/rail separation, door must be allowed to hang through a complete heating and cooling season.

Interior doors are for interior use only; exposure to extreme humidity, moisture, or temperatures may cause delaminating, checking, warping and raised grain. Proper care and storage should be considered when handling this product.

This Warranty Does Not Cover:

- Damage due to failure to follow proper installation, care, or maintenance instructions
- Damage due to failure to seal all six sides of the product within 30 days of invoice date
- · Any doors that have been cut-down in size or altered from original state
- · Appearance of field finishing
- Misalignment or shrinkage of panels, this is not considered a defect
- · Scratched glass
- Damage caused by attempting to repair the product
- Damage caused by others or by any cause beyond the control of Bayer Built Woodworks, including normal wear and tear, customer misuse, abuse, fire, flood, storm, or other acts of nature
- Fading or discoloration due to UV or sunlight exposure
- · Natural variations in the color and/or texture of the wood
- Exposure to acids, chemicals, or fumes
- Doors hung in exterior applications
- Water related damages
- Louver warping caused by moisture and humidity

Bayer Built Woodworks maximum liability is the purchase price of the product; finish and installation costs are not covered by this warranty.

BAYER BUILT WOODWORKS SPECIFICALLY EXCLUDES ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE.

BUYERS SOLE AND EXCLUSIVE REMEDY FOR DAMAGES IS EITHER REPAIR OR REPLACEMENT OF THE PRODUCT AND SELLER SPECIFICALLY EXCLUDES ANY DAMAGES INCLUDING, BUT NOT LIMITED, TO CONSEQUENTIAL OR INCIDENTAL DAMAGES.

Warranties are non-transferable